



**Proposed Bridge Rehabilitation for the Featherbed
Lane (John G. Lewis Memorial) bridge (No. 6051) over
the Catoctin Creek**

July 23, 2015

Raymond Ezell, RPA

District Archaeologist

(540) 654-1737

Raymond.ezell@vdot.virginia.gov

Section 106 Process

Ann B. Miller

VDOT Senior Research Scientist & Chair, Virginia Historic Structures Task Group


The Virginia Center For Transportation Innovation And Research

Section 106 Process

- **Cultural Resources Identification Status**
 - **Area of Potential Effects for Cultural Resources**
 - Archaeology-Project Footprint/Easements
 - Historic Architecture-Larger areas that have unobstructed views to and from the project
 - **Architecture and Archaeology**
 - Several previously identified cultural resources are present in the immediate vicinity of the project
 - Phase I Cultural Resources Survey is complete
 - **Civil War Battlefields**
 - The project is not located within any identified battlefields

Section 106 Process

Location of the Area of Potential Effects (APE)



Section 106 Process

Location of Previously
Recorded Resources

Information on this slide contains the locations of sensitive archaeological sites and is not available to the Public

Section 106 Process Archaeological Survey

o Negative shovel test

Information on this slide contains the locations of sensitive archaeological sites and is not available to the Public


Section 106 Process Archaeological Survey

This single Late Archaic (3000-1500 BC) projectile is the most notable archaeological find in the APE



Section 106 Process

Architectural Survey



Section 106 Process

Results of Architectural Survey

VDHR ID	Property Name Property Address	Property Description	VLR/ NRHP Status	JMA Recommendations
053-0131	John G. Lewis Bridge (Catoctin Creek Bridge/Bridge 6051) Featherbed Lane over Catoctin Creek	Single-span Pratt through-truss bridge.	Listed on VLR 1/24/1974, listed on NRHP 7/25/1974	JMA recommends no change in this resource's NRHP or VLR eligibility status.
053-0326	Roach/Cooper Miller's House Featherbed Lane	This resource is no longer extant	No formal eligibility determination by DHR	JMA recommends this resource not eligible for the VLR / NRHP because it has been demolished
053-6407	House 40701 Featherbed Lane	2-story tall, cross- gabled roof, eighteenth century vernacular house with board-and- batten exterior, rubble stone shed, and small barn	Previously unrecorded	JMA recommends this resource not eligible for the VLR / NRHP because it is not a significant example of an 18th century vernacular dwelling and modern alterations have lessened integrity of design and materials


No indication of an historic district in this vicinity

Section 106 Process Management Recommendations

VDHR ID	JMA recommendations
44LD1303	The identified components are not eligible to the NRHP; no further work is recommended. Construction activities should avoid the buried surface in the northern portion of the site. If not possible further work is recommended to investigate the deeply buried surface in ST J5.
44LD0058	The identified components are not eligible to the NRHP; no further work is recommended. Construction activities should avoid the buried surface in the northern portion of the site. If not possible further work is recommended to investigate the deeply buried surface in ST 16.5.
053-0131	Listed on VLR 1/24/1974, listed on NRHP 7/25/1974; JMA recommends no change in the VLR/NRHP status.
053-0326	Previously surveyed, no formal eligibility determination by DHR; JMA recommends this resource not eligible for the VLR/NRHP.
053-6407	Previously unrecorded; JMA recommends this resource not eligible for the VLR / NRHP.

Section 106 Process

We Are Here



Section 106 Process

Adverse Effects...What are they?

- An Adverse Effect is when an undertaking (project) directly or indirectly alters the characteristics of an historic property that qualifies it for inclusion in the National Register *in a manner that diminishes the integrity of property's location, design, setting, materials, workmanship, feeling, or association*
- What are the property's character defining features?
- Examples of Adverse Effects:
 - partial or total demolition
 - restoration, rehabilitation, repair, maintenance, stabilization, hazardous material remediation, or handicap access that is not consistent with the Secretary of the Interior's standards for the Treatment of Historic Properties

Section 106 Process

Next Steps

- **30-day review period of Phase I Cultural Resources report by the VDHR**
 - **Consulting Parties should provide comments on the Phase I report to me within the 30-day window.**
- **Address Adverse Effects of the Project on Historic Resources**
 - **Does the community have ideas for potential mitigation for the bridge project?**
- **Third anticipated Consulting Party meeting?**
 - **Tentative Topics to be Covered= Project Effect & Potential Mitigation Strategies**

Next Steps

- **Consulting Party Feedback/Questions**

**Can we agree to provide all written feedback to VDOT
by August 24?**