



TRAFFIC ALERT

VirginiaDOT.org

RELEASE: IMMEDIATE
CONTACT: Sharon Ketcham, (540) 829-7370 (office)
(540) 717-8376 (cell)
Sharon.Ketcham@VDOT.Virginia.gov

Sept. 4, 2023
CULP 2023-TA048

Lou Hatter, (540) 727-3201 (office)
(540) 717-2890 (cell)
Lou.Hatter@VDOT.Virginia.gov

U.S. 33 CROSSOVER TO CLOSE IN GREENE CO. FOR REPAIR WORK

Left turns at Stanardsville Bypass and Swift Run Rd. prohibited Thursday night

CULPEPER — Thursday night, Virginia Department of Transportation signal technicians will shut down the crossover at the intersection of U.S. 33 (Stanardsville Bypass) and Route 623 (Swift Run Road) to repair a traffic signal controller cabinet damaged in a motor vehicle crash.

To complete the work, VDOT will close the crossover from 9 p.m. to midnight, Thursday, Sept. 7.

Drivers headed west on the bypass who want to turn south onto Swift Run Road will have to continue west to Route 622 (Celt Road) and make a U-turn. Drivers headed east on the bypass who want to turn left onto U.S. 33 (Spotswood Trail) will have to continue through the intersection and make a U-turn at Route 609 (Fredericksburg Road).

Drivers northbound on Swift Run Road who want to travel west on the bypass or cross over to Spotswood Trail will instead turn right and make a U-turn at Fredericksburg Road. Motorists heading south on Spotswood Trail who want to cross the bypass to Swift Run Road, or head east on the bypass will instead turn west and make the U-turn at Celt Road.

Visit 511Virginia.org for the latest road conditions before traveling.

VDOT's Customer Service Center is open 24 hours a day to answer questions and take reports of roadway hazards. Call **1-800-FOR-ROAD (367-7623)** or contact us online at <https://my.vdot.virginia.gov>.

(END)